



USE COPPER OR ALUMINUM WIRE

230/2108-60-3

Fuse A - 50A 15sec Delay  
 Fuse B - 10A Standard

FACTORY WIRING	FIELD WIRING
Low Voltage	-----
High Voltage	-----

⚠ If there is an X1 and X2 terminal on 067211183, then connect them together and connect from C to either one.

⚠ For 208V operation, move this wire to 208V transformer tap

MODEL 60R1 Z  
 HEAT PUMP  
 W/9RW

4073-270 B