


If there is an R1 and R2 terminal on (16/41111),  
 jumper them together and connect from C to either one.

1. 200V operation move this tap to 230V transformer tap.

Electric WIRING	FIELD WIRING
Low Voltage	-----
High Voltage	-----

MAIN HEAT  
 9, 12, 15 Pa



USE COPPER FOR ALUMINUM WIRE