




	FACTORY WIRING	FIELD WIRING
Low Voltage	—	- - -
High Voltage	- - -	—

USE COPPER OR ALUMINUM WIRE

- ⚠ USED ON HAC30 MODELS ONLY.
- ⚠ HAC30 : 35/5 - 370
- ⚠ HAC36 : 35/5 - 440
- ⚠ FOR 208V. OPERATION MOVE THIS WIRE TO 208V. TRANSFORMER TAP.
- ⚠ HAC30 : 35A
- ⚠ HAC36 : 50A