




	FACTORY WIRING	FIELD WIRING
Low Voltage	—	- - -
High Voltage	- - -	—

USE COPPER OR ALUMINUM WIRE

⚠️ MAC30 : 40/370
 MAC36 : 35/440
 ⚠️ FOR 208V. OPERATION MOVE THIS WIRE TO 208V. TRANSFORMER TAP.