




	FACTORY WIRING	FIELD WIRING
Low Voltage	—	---
High Voltage	---	---

USE COPPER OR ALUMINUM WIRE

- △ HACR : 35/5 - 370
- △ HACR : 35/5 - 440
- △ FOR 208V. OPERATION MOVE THIS WIRE TO 208V. TRANSFORMER TAP.

NOTE: FUSE A - 60A TIME DELAY
FUSE B - 30A
ALL FUSES TYPE K-5