




230/208-60-1

	FACTORY WIRING	FIELD WIRING
Low Voltage	—	---
High Voltage	—	---

USE COPPER CONDUCTORS ONLY

- ⚠ USED ON NAC30 MODELS ONLY.
- ⚠ NAC30 : 35/5 - 370
- ⚠ NAC36 : 35/5 - 440
- ⚠ FOR 208V. OPERATION MOVE THIS WIRE TO 208V. TRANSFORMER TAP.