




- ⚠ Add jumper Rc to Rh. Set heat anticipator for W1 and W2 at .40A.
- ⚠ Remove jumper W1-W2 for 2-stage heat.
- ⚠ For 194V operation move this wire to 194V transformer tap.