



⚠ If there is an X1 and X2 terminal on 4674L1181, jumper them together and connect from C to either one.

USE COPPER OR ALUMINUM WIRE	FACTORY WIRING	FIELD WIRING
	Low Voltage	-----
	High Voltage	-----

MODEL 60601-3
HEAT PUMP
O.P.W.

230/208-60-3

⚠ For 208V operation move this wire to 208V transformer tap **407820**