




- ⚠ USED ON MAC30 MODELS ONLY.
- ⚠ MAC30 : 40/370
MAC35 : 35/440
- ⚠ FOR 208V. OPERATION MOVE THIS WIRE TO 208V. TRANSFORMER TAP.

	FACTORY WIRING	FIELD WIRING
Low Voltage	—	- - - -
High Voltage	—	- - - -

USE COPPER OR ALUMINUM WIRE