




FACTORY WIRING
Low Voltage ———
High Voltage ———

⚠ For 208V operation move this wire to 208V transformer tap.

CHART A	
MODEL NO.	RUN CAP.
MHP30A	35/370
MHP36A	35/440