



USE COPPER OR ALUMINUM WIRE

CHART A	
Fuse A	30A TP
Fuse B	60A STANDARD
FUSE C	30A STANDARD
All fuses Class K5.	

FACTORY WIRING	FIELD WIRING
Low Voltage	-----
High Voltage	- - - - -

45WH - 45/40  
42WH - 40/40

⚠ If there is an X1 and X2 terminal on 0674L1181, jumper them together and connect from C to either one.

⚠ For 208V operation move this wire to 208V transformer tap.