



- ⚠ IF THERE IS NO X1 AND X2 TERMINAL ON 6074L1101, JAMPER THEM TOGETHER AND CONNECT FROM C TO EITHER ONE.
- ⚠ FOR 200V OPERATION HAVE THIS WIRE TO 200V TRANSFORMER TAP.
- ⚠ 4089G - 40/440 CAPACITOR
- ⚠ 6081H - 45/440 CAPACITOR

	FACTORY WIRING	FIELD WIRING
Low Voltage	_____	-----
High Voltage	_____	-----

USE COPPER OR ALUMINUM WIRE

4089-113