



- ⚠ IF THERE IS AN X1 AND X2 TERMINAL ON 0674L1181, JUMPER THEM TOGETHER AND CONNECT FROM C TO EITHER ONE
- ⚠ FOR 208V OPERATION REMOVE THIS WIRE TO 208V TRANSFORMER TAP
- FUSE A - 60A TIME DELAY
- FUSE B - 60A STANDARD
- FUSE C - 30A STANDARD
- ALL FUSES CLASS K5

FACTORY WIRING
FIELD WIRING
USE COPPER OR AN EQUIV. WIRE

Low Voltage: _____
 High Voltage: _____