



⚠ For 208V operation move this wire to 208V transformer tap.



⚠ For 208V operation move this wire to 208V transformer tap.




230/208-60-1

USE COPPER OR ALUMINUM WIRE


	FACTORY WIRING	FIELD WIRING
Low Voltage	—	---
High Voltage	—	---

40124111

For 208V operation move this wire to 202V transformer tap.




⚠ For 208V operation move this wire to 208V transformer tap.



FACTORY WIRING	FIELD WIRING
Low Voltage	---
High Voltage	---


4012-121 E

For 208V operation note this
 wire to 208V transformer tap.




4012-330 Q

⚠ For 208V operation move this wire to 208V transformer tap.



⚠ 2nd heat contactor operates only during emergency heat or compressor cutoff.

⚠ For 208V operation move this wire to 208V transformer tap.



⚠ 2nd heat contactor operated only during emergency heat or compressor cutoff.

⚠ For 208V operation, move this wire to 208V transformer tap.

