

**USE COPPER  
CONDUCTORS ONLY**

- ⚠ Set heat anticipators at .40A for W1 and W2.
- ⚠ Reroute jumper from X2-W2 to X2-E.


Fused  
Disconnect  
Switch


230V 60 Hz 3-Ph

Factory Wiring ———  
Field Wiring - - - -

**MODEL  
36WH1**

4013-210 Rev.A





- ① Set heat anticipators at .40A for W1 and W2.
- ② Reroute jumper from X2-W2 to X2-E.
- ③ 6Kw heater operates only when compressor is shut off by emergency heat relay

MODEL  
36WH1  
w/15kw

Rev. A  
4013-230

230V 60 Hz 3-Ph

Field Wiring - - - -  
Factory Wiring \_\_\_\_\_