


If there is an R1 and R2 terminal on 06741101, jumper them together and connect from C to either one.

For 208V operation move this wire to 208V transformer tap.

FACILITY WIRING	FIELD WIRING
Low Voltage	-----
High Voltage	-----

MODEL'S  
R2011-3-0010-1  
Heat Pump  
0-1-W

4011-3102




If there is an X1 and X7 terminal on QS/4C1101, Jumper them together and connect from C to either one.

For 208V operation move this wire to 230V transformer tap.

FACTORY WIRING	FIELD WIRING
Low Voltage	-----
High Voltage	—————

MODELS  
42W4 3, 485, H5 3  
Heat Pump,  
9, 12, 15 kW

1014 3/70



Electric Heater  
 1500 watts  
 220V  
 1500 watts  
 110V

400-00-7

IF COOPER OR ALTERNATE WIRE

If there is an X1 and X2 terminal on 4674L1181, jumper them together and connect from C to either one.

For 200V operation have this wire to 200V transformer tap.

MODEL  
 19611  
 PART NO. 9, 12, 15 etc

FACTORY WIRING	FIELD WIRING
Low Voltage	-----
High Voltage	-----

4014-321

