




MOEL
36WA4

FACTORY WIRING	FIELD WIRING
Low Voltage	-----
High Voltage	-----

4009-III E