




230V/208-60-1

USE COPPER OR ALUMINUM WIRE

4081-122

USED ON HAC30 MODELS ONLY.

HAC30 : 35/5 - 370

HAC36 : 35/5 - 440

FOR 208V. OPERATION MOVE THIS WIRE TO 208V. TRANSFORMER TAP.

	FACTORY WIRING	FIELD WIRING
Low Voltage	—	---
High Voltage	---	---