


1074M1024/0674E1261

1074M1125/0674E1181



- ⚠ IF THERE IS AN X1 AND X2 TERMINAL ON 0674M1101, JUMPER THEM TOGETHER AND CONNECT FROM C TO EITHER ONE.
- ⚠ FOR LOW SPEED OPERATION, DISCONNECT THE BLACK MOTOR LEAD AND CONNECT IT TO THE ORANGE MOTOR LEAD. CONNECT THE RED MOTOR LEAD TO BLOWER RELAY TERMINAL NUMBER 1.

	FACTORY WIRING	FIELD WIRING
Low Voltage	_____	_____
High Voltage	_____	_____

USE COPPER OR ALUMINUM WIRE

460-60-3

4099 310B