







- ① Capacitor provides off-cycle crankcase heat.
- ② Set heat anticipators at .40A for W1 and W2.
- ③ Recuts jumper from X2-W2 to X2-E.

USE COPPER OR ALUMINUM WIRE

Factory Wiring ———  
Field Wiring - - - -

MODEL  
30MK  
w/3KW

230V 60 Hz 1-Ph

